

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

## Inspection Report Minerals Regulatory Program April 11, 2012

Reviewed:



Mine Name: Levan Henry	Permit Number: M/023/0023		
Operator Name: Sunroc	Inspection Date: 3/29/2012		
Inspector(s): Wayne Western	Time: 12:50-1:20 pm		
Other Participants: none	Mine Status: ACT		
Weather Condition: cool and clear skies	Last Inspection: 07/13/2010		
Bond Renewal Date: May 8, 2012	Bond Amount: \$99,735		
Surface Ownership: USFS/FEE	Mineral Ownership: Fee		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer,		$\boxtimes$	
2.	Bond/Bond Release	$\boxtimes$		
3.	Annual Fees	$\boxtimes$		
4.	Annual Report	$\boxtimes$		
5.	Public Safety (shafts, adits, trash, signs, highwalls)			
6.	Protection of Drainages / Erosion Control			
7.	Deleterious Material			
8.	Roads (maintenance, surfacing, dust control, safety)			
9.	Concurrent Reclamation			
10.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
11.	Water Impoundments			
12.	Soils			
13.	Re-vegetation			
14.	Air Quality			
15.	Other			

### **Purpose of Inspection:**

This was a routine inspection.

#### **Inspection Summary:**

In the approved Notice of Intent (NOI) approved acerage as 8.71 acres. The disturbed area map approved January 30, 2012 shows

Access Road	1.56 acres
Retention Basin	0.09 acres
Fine Stockpile	1.97 acres
Crusher Area	2.18 acres
Current Mine	4,32 acres
Total	10.12 acre

Inspection Date: March 29, 2012 Page 2 of 4 M/023/0023

In addition, there are some previous disturbed areas marked on the map but no acreage is given.

The 2011 annual report states that the permitted area is 13.00 acres.

The Permittee is in the process of expanding the mine to 40 acres. The bond appears to be adequate to reclaim the existing site in the event of bond forfeiture.

Last production reported was 2009.

Access to the site is through a locked gate. There were fire pits and alcohol bottles on site which suggests partiers could be visiting the site.

#### **Conclusions and Recommendations:**

The Division should continue to inspect the site on an annual basis. Also if the expansion is not approved then the NOI should be amended to show the current disturbance.

#### **Directions to Site:**

The turn off is approximately 2.5 miles south of Levan. Pit can be seen from the highway.

grayer Water

Inspector's Signature

WHW:

cc: (OPERATOR) Karl Boyer, USFS


O:\M023-Juab\M0230023-Henry I and 2\inspections\Insp-040502121.doc




Entrance to mine site



Pit bottom



Rilles and gullies on outslope



Stockpile